

Customer Quality Clause Update Worksheet

**CUSTOMER** Air Electro, Inc  
 QCPO-001 Rev. B

**CODE**

<b>F / AEIAC-01</b>	<b>Certification of Comformance</b>	Must be legible and reproducible.
<b>S</b>	<b>Foreign Object Debris/Damage (FOD) Prevention Program</b>	FOD awareness training must be given.
<b>U</b>	<b>First Article Inspection Report</b>	Using AS9102
<b>V</b>	<b>Counterfeit Parts Prevention</b>	Requirements of AS6174 and/or AS5553
<b>Y</b>	<b>Maintenance of Records</b>	Must be retained at least (10) years.
<b>Z</b>	<b>Temperature &amp; Shelf Life Sensitive Material</b>	Shall have a minimum of 80% remaining shelf life upon receipt.
<b>AEIAC-02</b>	<b>Material Certification, Chemical, Physical Test Data, Lot Traceability</b>	All certification shall contain all information required by Clause F and maintained by Clause Y
<b>AEIAC-03</b>	<b>Dimensional Inspection Report</b>	Shall furnish an inspection report for each lot of parts submitted, including inspections of critical features on drawing callouts.
<b>AEIAC-05</b>	<b>Source Inspection</b>	Notify QM 2 working days in advance
<b>AEIAC-15</b>	<b>Production Part Approval Process (PPAP)</b>	Representative fr QA or Eng'g will identify the appropriate PPAP submission level and add'l requirements for the part or component to be sourced.
<b>AEIAC-18</b>	<b>ROHS Compliance</b>	Compliance to the RoHS Directive regulations (2002/95/EC) required.
<b>AEIAC-20</b>	<b>REACH Compliance</b>	Compliance to Regulation (EC) No. 1907/2006 shall be adhered to in the manufacturing of product supplied.
<b>AEIAC-24</b>	<b>MSDS (SDS)</b>	Meets OSHA hazard communication standard on all potetially hazardous chemicals or materials
	<b>check PO's for DO, DX, DPAS</b>	