

CUSTOMER

Alliance Space Systems
20013774 Rev "D"

CODE

Q1	C.O.C.	Insulation and Manufacturers C.O.C. s
Q2	Dimensional Inspection Report Required	Use Q.A. form QF-10 for this clause only ship with product.
Q3	Material Certification Required	Certifications/ chemical & physical actual results are required in accordance with the applicable P.O. specification
Q6	Source inspection required	Notify qualityengineer@alliancespacesystems.com minimum 2 days in advance to schedule inspection at Insko
Q7	FAI Required	USE AS9102 forms
Q14	Shelf Life	Minimum 75% at time of receipt at Space Alliance
Q28	Material Lot/Batch #s	Shall be from the same lot/batch# without exception.